





Metric & Imperial Thread Size Guide


Metric Thread Pitches




5.0 mm




4.5 mm




4.0 mm




3.5 mm




3.0 mm




2.5 mm




2.0 mm



1.75 mm



1.5 mm




1.25 mm



1.0 mm



0.8 mm




0.7 mm



0.5 mm


Imperial Thread Sizes




6 tpi




7 tpi




8 tpi




9 tpi




10 tpi



11 tpi




12 tpi




13 tpi



14 tpi



16 tpi



18 tpi




20 tpi



24 tpi



28 tpi



32 tpi



40 tpi



Scale Check: After printing measure scale above with a ruler to ensure correct scale.